

## Menu

HISTORY FILE MAP for year 2003


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

354.11:41-12:01: 20m 1024bps real-time data lost when DSS14 antenna went to brake mode. Antenna Servo Controller Assembly reset and antenna returned to point. DR G103859 refers.



351.18:07-18:16: 9m of real-time 512bps data lost due to a long bitrate transition from 1024bps to 512bps at DSS15. No DR was raised.